

This is an inactive product and is no longer being manufactured. It may have inventory able to be purchased.



## Item Overview

Item#: RK147AT-041-A2 **(Inactive)**

Model: [RKA5512EXA](#)

Type: Rotary

Version: RK Series

Application: HBP/AC - Air Conditioning

Refrigerant: R-22

Voltage/Frequency: 100V ~ 50Hz / 115V ~ 60Hz

## Specifications

<b>Dimensions - Height:</b>	<b>11.194</b>
<b>Dimensions - Width:</b>	<b>9.451</b>
<b>Dimensions - Length:</b>	<b>9.451</b>
<b>Dimensions Unit of Measure:</b>	<b>IN</b>
<b>Discharge Line Size:</b>	<b>3/8 in (9.52mm)</b>
<b>Suction Line Size:</b>	<b>3/8 in (9.52mm)</b>
<b>Grommet:</b>	<input checked="" type="checkbox"/>

## Replacement Parts

*Are you a European Customer? Please use the TParts Finder Tool for the most accurate, up-to-date replacement parts information.*

[Go TO TParts](#)

<b>Overload Kit:</b>	<b>K90-27</b>
<b>Relay Kit:</b>	<b>K71-19</b>
<b>Run Capacitor:</b>	<b>85PR370F20</b>

## Documents

[Sales Drawing \(EN\)](#)  
[Electrical Diagram \(EN\)](#)